



Dangerous goods accepted
 ISO ● SDA3 ▲
 Food trace
 Check-up/repair work
 Spare parts
 Heating: electro ● steam ▲
 Heating: warmwater ▼
 Documents: ECD ● other ▲
 IBC-Cleaning
 Tank-heritization
 Inspection
 BAM - G68 001 (Germany)
 Rail connection
 Pumping
 Drying

1. Grisard Bitumen BTB

Hochbergstr. 50
 4057 Basel
 ☎ + 41 (0) 61/63 84 44 01
 H. Falco
 Fax: + 41 (0) 61/6 32 07 73
 btb@grisard.ch
 www.grisard.ch



ISO	●	SDA3	▲	Food trace	Check-up/repair work	Spare parts	Heating: electro	●	steam	▲	Heating: warmwater	▼	Documents: ECD	●	other	▲	IBC-Cleaning	Tank-heritization	Inspection	BAM - G68 001 (Germany)	Rail connection	Pumping	Drying
	■	●	▲																		●	●	
Mo 8:00-18:00, Tue-Thu 6:30-18:00, Fri 6:30-16:00																							

4. Heller

Industriestr. 16
 4617 Gunzgen
 ☎ + 41 (0) 62/2 16 43 33
 Richard Heller
 Fax: + 41 (0) 62/2 16 35 43
 htg@bluewin.ch
 www.htg-fluessigtransporte.ch

ISO	●	SDA3	▲	Food trace	Check-up/repair work	Spare parts	Heating: electro	●	steam	▲	Heating: warmwater	▼	Documents: ECD	●	other	▲	IBC-Cleaning	Tank-heritization	Inspection	BAM - G68 001 (Germany)	Rail connection	Pumping	Drying
		●	▲																				
Mo-Fr: 7:00-12:00, 13:15-19:00, Sa on request 7:00-12:00																							

5. Hofer

Neue Aarburgerstr. 6
 4852 Rothrist
 ☎ + 41 (0) 62/7 94 03 70
 Mr. Dambonc, Mr. Rothen
 Fax: + 41 (0)62/7 94 02 41
 info@tanktransport.ch
 www.tanktransport.ch



ISO	●	SDA3	▲	Food trace	Check-up/repair work	Spare parts	Heating: electro	●	steam	▲	Heating: warmwater	▼	Documents: ECD	●	other	▲	IBC-Cleaning	Tank-heritization	Inspection	BAM - G68 001 (Germany)	Rail connection	Pumping	Drying
	■	●	▲																				●
Mo-Fr 7:00-17:30																							

6. Giezendanner

Juraweg 26
 4852 Rothrist
 ☎ + 41 (0) 62/7 85 70 70
 Mr. G. Nützi
 Fax: + 41 (0) 62/7 85 70 75
 g.nuetzi@giezendanner-rothrist.ch
 www.giezendanner-rothrist.ch



ISO	●	SDA3	▲	Food trace	Check-up/repair work	Spare parts	Heating: electro	●	steam	▲	Heating: warmwater	▼	Documents: ECD	●	other	▲	IBC-Cleaning	Tank-heritization	Inspection	BAM - G68 001 (Germany)	Rail connection	Pumping	Drying
	■	●	▲																				
On request																							